

## 14AM Prepared Magnaglo Bath

Date: 02/07/2017 Purchase Order: Batch #: 17B017

It is hereby certified that the above listed magnetic particle inspection material and batch number meets the require-ments of the following specifications:

- ASME Boiler and Pressure Vessel Code, Section V, 2004, 2007, 2010, 2013 and 2015 Edition, Nondestructive Examination, including 2005, 2006, 2008, 2009b and 2011a Addenda, Paragraph T-731(B) and Article 25 as applicable.
- ASME Boiler and Pressure Vessel Code, Section V 1995, 1998 and 2001 Edition, Nondestructive Examination, including 1995 Winder Addenda, 1999, 2000, 2002 and 2003 Addenda, Paragraphs T-752, T-731(B) and Article 25 as applicable.
- ASTM E-709-15, Paragraphs 8.1.3, 8.5.4, 8.5.4.1 and 8.5.5.
- ASTM E-1444/E1444M-16, Paragraphs 5.5.2 and 5.5.3.
- NAVSEA 250-1500-1, Rev 17 September 2007 including ACN 6, Para. 12.4.1.6., 12.4.2.3, 12.4.2.3.1, and 12.4.2.3.2.
- NAVSEA T9074-AS-GIB-010/271( April 30, 1997 including Notice 1, September 11, 2014 Rev. 1)
  Paragraphs 4.3.2.2, 4.3.2.3, 4.3.2.4 and 4.3.2.6.1.
- MIL-STD-2132D, February 11, 2003, Paragraphs 6.1.3, 6.2.3, 6.2.4, 6.2.5, 6.2.6 and 6.2.7.
- The flash point of the material is over 200° F when tested by the Pensky-Marten's Closed Cup Method (ASTM D-93).
- The vehicle meets the requirements of A-A-59230, July 7, 1998 including Notice 2.
- The vehicle meets the requirements of AMS 2641C, Rev. 2015-05. The vehicle is classified as Type 1 according to paragraph 1.3.

It is further certified that this material does not contain mercury as a basic element and that no mercury bearing equipment has been used in its manufacture.

Batch Numbers appear on labels of bulk containers and on bottoms of aerosol cans.

Mathew Plamoottil

Quality Assurance Manager

Mathew Plamonto

Laurie Marx

**Quality Control Manager** 

a Manx

155 Harlem Ave. Glenview, IL 60025 P: 1-847-657-5300